Code Symbols



Digit	Specification			
4	Standard			
5	Measured component	1st component	2nd component	
		CO	Without	B
		CO_2	Without	D
		CH_4	Without	E
		CO_2	CO	G
		CH_4	CO	H
		CO_2	CH_4	J
6	Gas inlet / outlet connection	Rc1/4		1
		NPT1/4		2
7	Analog output signal	DC4～20mA		1
		DC0～1V		2
		DC0～100mV		3
		DC0～10mV		4
8	Revision No.			1
9	1st component, 1st range	See the table 1,2,3.		□
10	1st component, 2nd range	See the table 1,2,3.		□
11	2nd component, 1st range	None		Y
		See the table 4,5,6.		□
12	2nd component, 2nd range	None		Y
		See the table 4,5,6.		□
13	Language	Japanese		1
		English		2
14	Option	None		Y
		With CP calculation output		A
		With contact I/O		B
		With contact I/O + CP calculation output		C
15	–	–		Y
16	Adjustment	Standard		A
		For heat treat furnace		B
		For converter		C
		Others		Z

Correspondence table of the possible measuring ranges

Table 1：Single-component analyzer［CO_2］

1st range \ 2nd range		Y	J	K	Q	L	M	N	V	W	P	X	R
		Without	0～1%	0～2%	0～3%	0～5%	0～10%	0～20%	0～25%	0～40%	0～50%	0～70%	0～100%
H	0～0.5%	○	○	○	○	-	-	-	-	-	-	-	-
J	0～1%	○	-	○	○	○	-	-	-	-	-	-	-
K	0～2%	○	-	-	○	○	○	-	-	-	-	-	-
Q	0～3%	○	-	-	-	○	○	-	-	-	-	-	-
L	0～5%	○	-	-	-	-	○	○	○	-	-	-	-
M	0～10%	○	-	-	-	-	-	○	○	○	○	-	-
N	0～20%	○	-	-	-	-	-	-	○	○	○	○	○
V	0～25%	○	-	-	-	-	-	-	-	○	○	○	○
W	0～40%	○	-	-	-	-	-	-	-	-	○	○	○
P	0～50%	○	-	-	-	-	-	-	-	-	-	○	○
X	0～70%	○	-	-	-	-	-	-	-	-	-	-	○
R	0～100%	○	-	-	-	-	-	-	-	-	-	-	-

Table 2：Single-component analyzer［CO］

1st range \ 2nd range		Y	J	K	Q	L	M	N	V	W	P	X	R
		Without	0～1%	0～2%	0～3%	0～5%	0～10%	0～20%	0～25%	0～40%	0～50%	0～70%	0～100%
H	0～0.5%	○	○	○	○	-	-	-	-	-	-	-	-
J	0～1%	○	-	○	○	○	-	-	-	-	-	-	-
K	0～2%	○	-	-	○	○	○	-	-	-	-	-	-
Q	0～3%	○	-	-	-	○	○	-	-	-	-	-	-
L	0～5%	○	-	-	-	-	○	○	○	-	-	-	-
M	0～10%	○	-	-	-	-	-	○	○	○	○	-	-
N	0～20%	○	-	-	-	-	-	-	○	○	○	○	○
V	0～25%	○	-	-	-	-	-	-	-	○	○	○	○
W	0～40%	○	-	-	-	-	-	-	-	-	○	○	○
P	0～50%	○	-	-	-	-	-	-	-	-	-	○	○
X	0～70%	○	-	-	-	-	-	-	-	-	-	-	○
R	0～100%	○	-	-	-	-	-	-	-	-	-	-	-

Table 3：Single-component analyzer［CH_4］

1st range \ 2nd range		Y	K	Q	L	M	N	V	W	P	X	R
		Without	0～2%	0～3%	0～5%	0～10%	0～20%	0～25%	0～40%	0～50%	0～70%	0～100%
J	0～1%	○	○	○	○	-	-	-	-	-	-	-
K	0～2%	○	-	○	○	○	-	-	-	-	-	-
Q	0～3%	○	-	-	○	○	-	-	-	-	-	-
L	0～5%	○	-	-	-	○	○	○	-	-	-	-
M	0～10%	○	-	-	-	-	○	○	○	○	-	-
N	0～20%	○	-	-	-	-	-	○	○	○	○	○
V	0～25%	○	-	-	-	-	-	-	○	○	○	○
W	0～40%	○	-	-	-	-	-	-	-	○	○	○
P	0～50%	○	-	-	-	-	-	-	-	-	○	○
X	0～70%	○	-	-	-	-	-	-	-	-	-	○
R	0～100%	○	-	-	-	-	-	-	-	-	-	-