

To All Customers

Rep No. B20039

January 12, 2021

Fuji Electric FA Components
& Systems Co., Ltd.

MS4S Series Timers

Notification regarding Change in Operation Indicator (LED)

We would like to thank you for your continued patronage of Fuji products.

We will be changing some products as described below.

Please review the following information and take appropriate actions.

Please also inform all related sections of your company of these changes.

Product name	Timer
Series name	MS4S Series
Type	MS4SM-AP, MS4SM-CE, MS4SM-DL MS4SA-AP, MS4SA-CE, MS4SA-DL MS4SC-AP, MS4SC-CE, MS4SC-DL MS4SY-AP
Changed parts	Operation indicator (LED)
Details of the change	The chip LED for the operation indicator will be changed. Compared to conventional products, the brightness of the indicator lamp will be increased and the visibility improved.
Reason for changes	To facilitate the procurement of LEDs
Date of the production change	Scheduled for products to be produced from June 2021
Attachment	Attachment: Comparison of Operation Indicator Appearances
Notes concerning the changes	This change will not affect product performance.

[Details of the change]

The chip LED for the operation indicator will be changed.

Compared to conventional products, the brightness of the indicator lamp will be increased and the visibility improved.

