

Certificate of Compliance

Certificate Number:

UL-US-2406622-0

Report Reference:

E42419-20240214

Issue Date:

2024-02-20

Issued to:

FUJI ELECTRIC FA COMPONENTS & SYSTEMS CO LTD FUKIAGE FACTORY 5-45 MINAMI, 1-CHOME KONOSU-SHI, Saitama 369-0192

Japan

This certificate confirms that representative samples of:

NLDX - Motor Controllers, Magnetic

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

UL 60947-1, 5th Ed., Issue Date: 2013-07-31, Revision Date: 2019-05-06, UL 60947-4-1, 3rd Ed., Issue Date: 2014-04-04, Revision Date: 2017-10-17

Additional Information:

See UL Product iQ® at https://ig.ulprospector.com for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



UL Mark Certification Program Manager



CERTIFICATE OF COMPLIANCE

Certificate number UL-US-2406622-0 Report reference E42419-20240214

Date 2024-02-20

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Model	Product Description
SC, followed by 20, 26, 32 or 38, followed by D or X, , followed by A or U, may be followed by H, may be followed by R, followed by -1, -2, -4, -5, -E, -F, -H, -K, -M, -P, -S, -T or -W, followed by 01, 02, 10, 11 or 20, may be followed by	Magnetic Motor Controllers
Z3. SC, followed by 20, 26, 32 or 38, followed by DG or XG, , may be followed by H, may be followed by R, followed by -1, -2, -B, -D, -E, -F, -G, -H, -K, -L, -M, -Q or -Y, followed by 01, 02, 10, 11 or 20, may be followed by Z3.	Magnetic Motor Controllers
SW, followed by 20, 26, 32 or 38, followed by D or X, followed by A or U, may be followed by H, may be followed by R, followed by 3 or K, followed by -1, -2, -4, -5, -E, -F, -H, -K, -M, -P, -S, -T or -W, followed by 01, 02, 10, 11 or 20, followed by T002, T003, T004, T005, T006, T007, T009, T012, T018, T020, T026, T032, T1P1, T1P4, T1P7, T2P2, T2P8, TP10, TP13, TP18, TP24, TP34, TP48, TP64, TP80, TP95, may be followed by Z3.	Magnetic Motor Controllers
SW, followed by 20, 26, 32 or 38, followed by DG or XG, , may be followed by H, may be followed by R, followed by 3 or K, followed by -1, -2, -B, -D, -E, -F, -G, -H, -K, -L, -M, -Q or -Y, followed by 01, 02, 10, 11 or 20, followed by T002, T003, T004, T005, T006, T007, T009, T012, T018, T020, T026, T032, T1P1, T1P4, T1P7, T2P2, T2P8, TP10, TP13, TP18, TP24, TP34, TP48, TP64, TP80, TP95, may be followed by Z3.	Magnetic Motor Controllers

David Piecuch

UL Mark Certification Program Manager





Certificate of Compliance

Certificate Number:

UL-CA-2405773-0

Report Reference:

E42419-20240214

Issue Date:

2024-02-20

Issued to:

FUJI ELECTRIC FA COMPONENTS & SYSTEMS CO LTD FUKIAGE FACTORY
5-45 MINAMI. 1-CHOME KONOSU-SHI. Saitama 369-0192

5-45 MINAMI, 1-CHOME KONOSU-SHI, Saitama 369-0192 Japan

This certificate confirms that representative samples of:

NLDX7 - Motor Controllers, Magnetic Certified for Canada

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

CSA C22.2 NO. 60947-4-1, 2nd Ed., Issue Date: 2014-04-04, Revised 2018-05, CSA C22.2 No. 60947-1, 2nd Ed., Issue Date: 2013-07-01

Additional Information:

See UL Product iQ® at https://iq.ulprospector.com for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



UL Mark Certification Program Manager



CERTIFICATE OF COMPLIANCE

Certificate number UL-CA-2405773-0 Report reference E42419-20240214

Date 2024-02-20

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Model	Product Description
SC, followed by 20, 26, 32 or 38, followed by D or X, followed by A or U, may be followed by H, may be followed by R, followed by -1, -2, -4, -5, -E, -F, -H, -K, -M, -P, -S, -T or -W, followed by 01, 02, 10, 11 or 20, may be followed by Z3.	Magnetic Motor Controllers
SC, followed by 20, 26, 32 or 38, followed by DG or XG, , may be followed by H, may be followed by R, followed by -1, -2, -B, -D, -E, -F, -G, -H, -K, -L, -M, -Q or -Y, followed by 01, 02, 10, 11 or 20, may be followed by Z3.	Magnetic Motor Controllers
SW, followed by 20, 26, 32 or 38, followed by D or X, followed by A or U, may be followed by H, may be followed by R, followed by 3 or K, followed by -1, -2, -4, -5, -E, -F, -H, -K, -M, -P, -S, -T or -W, followed by 01, 02, 10, 11 or 20, followed by T002, T003, T004, T005, T006, T007, T009, T012, T018, T020, T026, T032, T1P1, T1P4, T1P7, T2P2, T2P8, TP10, TP13, TP18, TP24, TP34, TP48, TP64, TP80, TP95, may be followed by Z3.	Magnetic Motor Controllers
SW, followed by 20, 26, 32 or 38, followed by DG or XG, , may be followed by H, may be followed by R, followed by 3 or K, followed by -1, -2, -B, -D, -E, -F, -G, -H, -K, -L, -M, -Q or -Y, followed by 01, 02, 10, 11 or 20, followed by T002, T003, T004, T005, T006, T007, T009, T012, T018, T020, T026, T032, T1P1, T1P4, T1P7, T2P2, T2P8, TP10, TP13, TP18, TP24, TP34, TP48, TP64, TP80, TP95, may be followed by Z3.	Magnetic Motor Controllers

David Piecuch

UL Mark Certification Program Manager

