

Certificate of Compliance

Certificate Number:

UL-US-2422575-0

Report Reference:

E42419-20240610

Issue Date:

2024-06-11

Issued to:

**FUJI ELECTRIC FA COMPONENTS & SYSTEMS CO LTD
FUKIAGE FACTORY
5-45 MINAMI, 1-CHOME KONOSU-SHI, Saitama 369-0192
Japan**

This certificate confirms that representative samples of:

NLDX - Motor Controllers, Magnetic

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

UL 60947-1, 5th Ed., Issue Date: 2013-07-31, Revision Date: 2019-05-06, UL 60947-4-1, 3rd Ed., Issue Date: 2014-04-04, Revision Date: 2017-10-17

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch
UL Mark Certification Program Manager



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

CERTIFICATE OF COMPLIANCE

Certificate number UL-US-2422575-0
Report reference E42419-20240610
Date 2024-06-11

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

| Model | Product Description |
|---|----------------------------|
| SC, followed by 40X, 50X or 65X, , followed by A or U, may be followed by H, may be followed by R, followed by -1, -2, -4, -5, -C, -E, -F, -G, -H, -J, -K, -L, -M, -N, -P, -Q, -R, -S, -T, -U, -V, -W, -X or -Y, followed by 11, may be followed by Z3. | Magnetic Motor Controllers |
| SC, followed by 40XG, 50XG or 65XG, , may be followed by H, may be followed by R, followed by -1, -2, -B, -D, -E, -F, -G, -H, -K, -M, -Q or -Y, followed by 11, may be followed by Z3. | Magnetic Motor Controllers |
| SW, followed by 40X, 50X or 65X, , followed by A or U, may be followed by H, may be followed by R, followed by 3 or K, followed by -1, -2, -4, -5, -C, -E, -F, -G, -H, -J, -K, -L, -M, -N, -P, -Q, -R, -S, -T, -U, -V, -W, -X or -Y, followed by 11, followed by T004, T005, T006, T007, T009, T012, T018, T024, T032, T036, T044 or T053, may be followed by Z3. | Magnetic Motor Controllers |
| SW, followed by 40XG, 50XG or 65XG, , may be followed by H, may be followed by R, followed by 3 or K, followed by -1, -2, -B, -D, -E, -F, -G, -H, -K, -M, -Q or -Y, followed by 11, followed by T004, T005, T006, T007, T009, T012, T018, T024, T032, T036, T044 or T053, may be followed by Z3. | Magnetic Motor Controllers |



David Piecuch
UL Mark Certification Program Manager

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.



Certificate of Compliance

Certificate Number:

UL-CA-2417926-0

Report Reference:

E42419-20240610

Issue Date:

2024-06-11

Issued to:

**FUJI ELECTRIC FA COMPONENTS & SYSTEMS CO LTD
FUKIAGE FACTORY
5-45 MINAMI, 1-CHOME KONOSU-SHI, Saitama 369-0192
Japan**

This certificate confirms that representative samples of:

NLDX7 - Motor Controllers, Magnetic Certified for Canada

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

**CSA C22.2 No. 60947-1, 2nd Ed., Issue Date: 2013-07-01, CSA
C22.2 NO. 60947-4-1, 2nd Ed., Issue Date: 2014-04-04, Revised
2018-05**

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



A handwritten signature in black ink, appearing to read 'David Piecuch'.

David Piecuch
UL Mark Certification Program Manager

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

CERTIFICATE OF COMPLIANCE

Certificate number UL-CA-2417926-0
Report reference E42419-20240610
Date 2024-06-11

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

| Model | Product Description |
|---|----------------------------|
| SC, followed by 40X, 50X or 65X, , followed by A or U, may be followed by H, may be followed by R, followed by -1, -2, -4, -5, -C, -E, -F, -G, -H, -J, -K, -L, -M, -N, -P, -Q, -R, -S, -T, -U, -V, -W, -X or -Y, followed by 11, may be followed by Z3. | Magnetic Motor Controllers |
| SC, followed by 40XG, 50XG or 65XG, , may be followed by H, may be followed by R, followed by -1, -2, -B, -D, -E, -F, -G, -H, -K, -M, -Q or -Y, followed by 11, may be followed by Z3. | Magnetic Motor Controllers |
| SW, followed by 40X, 50X or 65X, , followed by A or U, may be followed by H, may be followed by R, followed by 3 or K, followed by -1, -2, -4, -5, -C, -E, -F, -G, -H, -J, -K, -L, -M, -N, -P, -Q, -R, -S, -T, -U, -V, -W, -X or -Y, followed by 11, followed by T004, T005, T006, T007, T009, T012, T018, T024, T032, T036, T044 or T053, may be followed by Z3. | Magnetic Motor Controllers |
| SW, followed by 40XG, 50XG or 65XG, , may be followed by H, may be followed by R, followed by 3 or K, followed by -1, -2, -B, -D, -E, -F, -G, -H, -K, -M, -Q or -Y, followed by 11, followed by T004, T005, T006, T007, T009, T012, T018, T024, T032, T036, T044 or T053, may be followed by Z3. | Magnetic Motor Controllers |



David Piecuch
UL Mark Certification Program Manager

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

